

MSDS**Material Safety Data Sheet**

24 HOUR EMERGENCY TELEPHONE NUMBER CALL CHEMTREC 1-800-424-9300
--

189 Twin County Road • Morgantown, PA 19543 • (610) 524-5810

Solution D, Fixative (Wescor)

Section I: PRODUCT IDENTIFICATION

Name: Solution D, Fixative (for use on the Wescor Aerosprayer®)

Azer Scientific Product Number: ES946, ES948

Product Description: Methyl Alcohol

Cas No: 67-56-1

Formula: NA

Revision Date: 22 January 2007

Section II: HAZARDOUS INGREDIENTS / EXPOSURE LIMITS

<i>Hazardous Component(s):</i>	<i>CAS Number</i>	<i>OHSA PEL, ACGIH TLV/STEL</i>
Methyl Alcohol 100%	67-56-1	200/250

NFPA

Health	1
Flammability	3
Reactivity	0

Section III: PHYSICAL / CHEMICAL COMPOSITION

<i>Boiling Point:</i> 148°F	<i>Specific Gravity (H₂O = 1):</i> 0.79
<i>Vapor Pressure mm Hg/20°C:</i> 96	<i>Percent Volatile by Vol:</i> 91%
<i>Vapor Density (Air 1:1):</i> 1.11	<i>Evaporation Rate (ether = 1):</i> > 1
<i>Solubility in H₂O:</i> Complete	<i>Appearance & Odor:</i> Clear liquid/pungent odor

Section IV: FIRE/EXPLOSION HAZARD DATA

Flash Point: 54°F TCC *Flammable Limits:* LEL 6.7 UEL 36.5
Extinguishing Media: Water Spray, Dry Chemical, CO₂ and Foam for Alcohol

Special Fire Fighting Procedures: Wear protective clothing with NIOSH approved breathing apparatus. Products of combustion may be harmful in a fire situation. Do not use direct water stream.

Unusual Fire & Explosion Hazards: Eliminate sources of ignition. Burns with invisible flame.

Section V: REACTIVITY DATA

Stability: Stable

Material to Avoid: Strong oxidizers, chromic anhydride, perchloric acids, etc.

Hazardous Decomposition or Byproducts: Oxides of carbon.

Hazardous Polymerization: Does not occur

Conditions to Avoid: Excessive heat, sparks or flames.

Section VI: HEALTH HAZARD DATA

Routes of Entry: Inhalation, Skin and Ingestion

Acute: Vapors may cause eyes, skin and respiratory irritation, drowsiness, nausea, headache and vomiting.

Chronic: May cause liver, heart and kidney damage. May cause gastrointestinal disturbances and convulsions.

Carcinogenicity: Not classified as a human carcinogen.

Signs/Symptoms of Exposure: Vision blurring, drowsiness and headache.

******* Emergency First Aid *******

Skin: Remove contaminated clothing and change. Wash affected skin area with soap and water.

Eyes: Thoroughly flush eyes with water. Contact a physician if irritation persists.

Ingestion: Rinse mouth thoroughly with water, provided person is conscious and contact a physician.

Inhalation: Remove person to fresh air. If not breathing, give artificial respiration and contact physician.

Section VII: SAFE HANDLING

Chemical Release or Spill: Eliminate source of ignition in the vicinity of the spill or released vapor. Isolate the spill area with sand, or other absorbent material. Place all contaminated material in close container for disposal.

Waste Disposal Method: All liquid and or contaminated material should be disposed of in DOT approved waste containers. Comply with all Federal, State and Local regulations for disposal.

Precautions for Handling and Storing: Use precautions for flammable liquids. Avoid excessive heat and sources of ignition. For large quantities, store in flammable safety cabinet. Use in well-ventilated area.

Section VIII: CONTROL MEASURES

Respiratory Protection: Not normally required. If used in a poorly ventilated area use under an approved fume hood or NIOSH approved respirator.

Ventilation: Special flammable exhaust hood if vapor concentration is high. In well-ventilated areas, mechanical exhaust is sufficient.

Protective Gloves: Chemical resistant.

Eye Protection: Safety glasses.

Other Protective Clothing or Equipment: Normal laboratory apparel suggested by Good Laboratory Practices.

Work/Hygienic Practices: Wash thoroughly with soap and water after handling.

AZER SCIENTIFIC INC. MAKES NO REPRESENTATION AS TO THE COMPREHENSIVENESS OR ACCURACY OF THIS INFORMATION. INDIVIDUALS RECEIVING THIS INFORMATION MUST EXERCISE THEIR INDEPENDENT JUDGMENT IN DETERMINING ITS APPROPRIATENESS FOR A PARTICULAR PURPOSE. ACCORDINGLY, AZER SCIENTIFIC INC. WILL NOT BE RESPONSIBLE FOR DAMAGES OF ANY KIND OR NATURE RESULTING FROM THE USE OF ANY SUCH INFORMATION. NO REPRESENTATIONS OR WARRANTIES OF ANY KIND OR NATURE, INCLUDING BUT NOT LIMITED TO, EXPRESS WARRANTIES, IMPLIED WARRANTIES OF MERCHANTABILITY, OR WARRANTIES OF FITNESS FOR A PARTICULAR PURPOSE, ARE MADE HEREUNDER WITH RESPECT TO THE INFORMATION SET FORTH HEREIN OR TO THE PRODUCT TO WHICH THE INFORMATION REFERS.